






These cables are needed for the connection panel on the back of the scanner.

- Mini USB to USB-B / Arduino Nano
- USB-A to USB-A / Raspberry PI
- Micro HDMI to HDMI / Raspberry PI
-all cables are preferably short 30-40cm

Input 12V / 3A
from external power supply*

Adjusted to 5.1v before connection
IMPORTANT!



I2C and Power to RPI
Flat Cable

